

RÓY C. CARLSON, PRES.
10600 SHERIDAN AVE. SO.
881-4870
55431

CERTIFICATE OF SURVEY

WILLIAM A. CARLSON, V.P.
2324 W. 110TH ST.
888-2084
55431



Survey for:


Lee Johnson

LAND SURVEYORS

Licensed, Insured & Bonded

Setback on Lot 10; 28.0'
Setback on Lot 13; 30.0'

Prop. garage el; 856.0



Legal description;
That part of Lot 12, Block 3,
Brookview Heights 3rd Addition,
lying North of a line drawn from the
most Southerly corner of Lot 10,
said Block 3, to the Southwesterly
corner of Lot 21, Block 7,
Brookview Heights 2nd Addition.

APPROVED

C. J. M.

**BUILDING INSPECTOR
VILLAGE OF EDINA**

We hereby certify that this is a true and correct representation of a survey of the land above described and of the location of all buildings, if any, thereon, and all visible encroachments, if any, from or on said land.

As surveyed by us this 31st day of August, 1968.

William A. Carlson

Minn. Reg. No. 5648